

FIG. 1





FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7





FIG. 8







FIG. 9



# FIG. 10

IMAGE FORMING APPARATUS 101

104 AUTOMATIC DOCUMENT FEEDER

SCANNER  
UNIT 103

PRINTER  
UNIT 102

105 SHEET POST-PROCESSING  
APPARATUS

106 MULTI-STAGE  
FEED UNIT




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15

301

	USER NAME/ MODE NAME	DATE/TIME OF RECEIPT	PAGE NUMBER	STATUS
1	OKAMOTO	14:15 12/09	007/015	IN PROGRESS 1/2
2	MATUMOTO	14:17 12/09	000/007	ON STANDBY
3	0743XXXXXX	14:18 12/09	000/003	ON STANDBY

JOB QUEUE  
 ⇄  
 COMPLETE

PRINT JOB

E-MAIL JOB

FAX JOB

A J ALL JOBS

INTERRUPT

FIG. 16




FIG. 17






FIG. 19




FIG. 20

201

PAPER JAM OCCURRED IN MAIN BODY.  
MOVE BOTH-SIDED UNIT.

FIG. 21




FIG. 22

201

HIGH CAPACITY TRAY IS OUT OF PAPER.  
SUPPLY PAPER.

FIG. 23




FIG. 24 (a)




FIG. 24 (b)




FIG. 25

201

SCANNER FUNCTION IS IN FAILURE.

FIG. 26 (a)

201

SCANNER FUNCTION IS IN FAILURE.

FIG. 26 (b)

201

PRINTING  
OKAMOTO MS-WORD

FIG. 27 (a)

201  
BOTH-SIDED FUNCTION IS IN FAILURE.

FIG. 27 (b)

201  
FINISHER IS IN FAILURE.


FIG. 27 (c)



201  
REPLACE STAPLE UNIT.

FIG. 27 (d)

201  
FEED TRAY 2 IS IN FAILURE.

FIG. 28





10037713 v.0.1.0.1.0.2

FIG. 30




FIG. 31

